Illinois Department of Transportation Structures Information Management System

Date: 3/2/2005 Page 1

Structure	013-9906	District:	7	•		
				Inventory	Data	
Facility Carried:	ICG RR		Bridge Name:	T5N R5E SEC 29	Sufficiency Rating:	C4
Feature Crossed:	TR-67		Location:	2 MI WNW IOLA	HBRRP Eligible:	Structure Length: 86.0
Bridge Remarks:	AASHTO BR LENG				Replaced By:	No AASHTO Bridge Length: 82.0 000-0000 Length of Long Span: 31.0
Bridge Status:	1 OPEN - NO RE	STRICT	StatusDate:	04/1988	Replaces:	
Status Remarks:					Last Update Date:	000-0000 Bridge Roadway Width: 0.0 07/19/1999 Appr Roadway Width: 0.0
Maint County:	013 CLAY	Maint To	wnship:		Parallel Structure:	None Deck Width: 0.0
Maint Responsibility:	06 RAILROAD				Multi-Level Structure	Nbr: Sidewalk Width Right: 0.0
Service On/Under:	2 RAILROAD		/ 1 Hi	GHWAY	Skew Direction:	None Sidewalk Width Left: 0.0
Reporting Agency: Main Span Matl/Type:	2 I.D.O.T BURE	EAU OF LOCAL I			Skew Angle: 00	D 00 M 00 S Navigation Control: N N/A
Nbr Of Main Spans:			/ 02 STRING	GER/MULTI-BEAM/GIRI		No Navigation Horiz Clear: 0
Approaches	3 Nbr Of Appro	oacn Spans:	0		Historical Significan	ce: No Navigation Vert Clear: 0
Near #1 Mati/Type:			,		Border Bridge St	ate: Culvert Fill Depth: 0.0
Near #2 Matl/Type:			/		Bdr State SN:	Number Culvert Cells: 0
Far #1 Mati/Type:			I		Bdr State % Resp	
Far #2 Matl/Type:			,		Structural Steel V	
Median Width/Type:	0 Ft. / 0 None		,		Detail Day N. Alfa	Culvert Cell Width: 0.00
Guardrail Type L/R:	0 None	/ 0 Nor	ne I	nventory Rating:	Rated By: N N/A 0.0 (NNN) Load Rating Date:	Rate Method:
Toll Facility Indicator:	0 No Toll			Operating Rating:	0.0 (NNN) Load Rating Date:	***Railroad Crossing Info***
Latitude: 38 D 36		tude: 82 D			KNOWN	Crossing 1 Nbr: 295097N
Deck Structure Type:	N N/A			ture Thickness:	0.0	Crossing 1 Nbr: RR Lateral Underclear: 00.0
Sidewalks Under Struct	ture: 0 None					RR Lateral Underclear: 00.0 RR Vertical Underclear: 00 Ft 00 In
	Ke	y Route On I	Data		Kou	Route Under Data
Key Route Nbr:		•	Station:		TOWNSHIP OR ROAD DISTRICT	
Appurtenances:			Segment:		Main Route 00,000	
Inventory County:			Linked:		013 CLAY	Segment: Linked: Y
Township/Road Dist:		i	Nati. Hwy System:		06 LARKINSBURG	Natl. Hwy System: Not on NHS
Municipality: Urban Area:			Inventory Direction:		0000	Inventory Direction:
Functional Class:			Curr AADT Yr/Coun	t: /	None	Curr AADT Yr/Count: 1997 / 59
** CLEARANCES ** Sou	uth/East Names		Est Truck Percentag	ge: %	60 LOCAL ROAD, (NON-URBAN)	Est Truck Percentage: 0 %
Max Rdwy Width:	uth/East North/W		Number Of Lanes:		South/East North/West	Number Of Lanes:
Horizontal:	•		One Or Two Way:		027.8	One Or Two Way: 2 Two-Way
h	Ft In Ft	ln i	Bypass Length:	_	027.8 000.0	Bypass Length: 0
	Ft In Ft		Future AADT Yr/Cnt		11 Ft 09 In 00 Ft 00 In	Future AADT Yr/Cnt: 2012 / 75
Lateral:		-	Designated Truck R Special Systems:	te:	11 Ft 09 in 00 Ft 00 in	Designated Truck Rte: NONE
	*** Mark	ed Route On	Deta ***		07.0 Ft 99.8 Ft	Special Systems: No
	Designation	en izonte Oli			*** Marke	d Route Under Data ***
Route #1:	~valghation		Kind	Number	Designation	Kind Number
Route #2:					1 Mainline	4 FAS, CH, or Tr's Unmarked 0067
Route #3:		•			•	5 to 5 to 5 timarica 5007

Date: 3/2/2005 Page 2

Tons

Tons

Tons

O Acr

0

٥

Structure

013-9906

District: 7

Data Related to Inspection Information

*** Maximum Allowable Posting Limits ***

Bridge Posting Level: 5 No Posting Required

Single Unit Vehicles:

Combination Type 3S-1:

Combination Type 3S-2:

One Truck At A Time:

** Actual Posted Limits **

Last Paint Type:

Routine NBIS: Fracture Critical:

0 MOS Underwater:

***Inspection Intervals ***

0 MOS One Truck At A Time: Combination Type 3S-1:

Tons

0 MOS Special:

0 MOS Single Unit Vehicles: Combination Type 3S-2:

Tons

Inspection/Appraisal Information Special Inspection Date:

Inspection Temperature:

Insp by (Name):

Utilities Attached:

Deck Wearing Surf:

Deck Membrane:

Deg.

Inspection Date: Deck:

Superstructure: Substructure:

Culvert:

Channel and Protection: Structural Evaluation: **Deck Geometry:**

Underclearance-Vert/Lat.: Waterway Adequacy: Approach Roadway Align: **Bridge Railing Appraisal:** Approach Guardrail:

Deck Protection: Total Deck Thick: Last Paint Date: Inspection Remarks:

Inspection Date: Temperature: Inspected By:

Inspection Category: Inspection Method:

Appraisal Rating:

Inspection Remarks:

Pier Navig Protection:

Scour Critical Information

Evaluation Method:

Analysis By:

Miscellaneous

Fracture Critical Members: No Microfilm Data Recorded: No

Construction Information Year: 1900 Original

Sta:

1981

Reconstructed Sta: Flood Design Frequency: Flood Design Q (CFS):

Flood Design Nat H W E: Flood Des Open Prop:

Flood Base Q (CFS): 0 SF Flood Base Nat H W E:

0 YR Drainage Area:

Fed Aid Pr #: **Built By:**

Route:

Section Nbr:

Contract Nbr:

Rating:

Analysis Date:

0000000000000 0 UNKNOWN

00000000000000

Len

*** Costs in Dollars ***

Bridge Roadwa Total

Waterway Information

Proposed Improvement

Underwater Inspection/Appraisal Information

Type of Done Rem

Cost

ILLINOIS COMMERCE COMMISSION STIPULATED AGREEMENT – CROSSING DATA FORM EXISTING RAILROAD OVER HIGHWAY STRUCTURE NO. 013-9904

GENERAL INFORMATION:

RAILROAD	Illinois Central Railroad Company		
USDOT#, MILEPOST	295 106k, 9.44-U		
STREET, CITY, COUNTY	CH 22, Near Iola, Clay County		
JURISDICTION (RDWY)	Clay County		
LOCATION	Rural, Agricultural		

ROADWAY DATA:

SURFACE	Two-Lane, Two-Way, East-West, 22-Foot, Oil and Chip Roadway
	with 2-Foot Aggregate Shoulders
ADT & SPEED	Existing: 70 Vehicles Per Day @ 30 MPH
	Projected (2012): 100 Vehicles Per Day @ 30 MPH
TRAFFIC TYPE	Passenger, Possible Hazmat, Possible Emergency Response
	(Current low clearance of approximately 11'-1" limits traffic types)

RAILROAD DATA:

TRACKS & DIRECTION	1 Set of North-South Tracks
FREIGHT TRAFFIC	10 Trains Per day @ 50 MPH, Day & Night
PASSENGER TRAFFIC	None

COMMENTS:

See Exhibit A-3, Pages 4 & 5: Illinois Department of Transportation, Master Structure Report.

The existing structure is a 3-span, steel beam structure designed for railroad traffic. The current vertical clearance is sub-standard. Improvement of the vertical clearance is part of a larger program to replace or close all of the sub-standard structures on the Illinois Central Railroad Company line in Clay County.

PROPOSED COST DIVISION:

Clay County ------ 40% Grade Crossing Protection Fund ----- 60%

Page 2 --- Location Sketch

Page 3 --- Photographs

Page 4, 5 --- IDOT, Master Structure Report